

AD-A068 675

NEW JERSEY STATE DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/G 13/2
NATIONAL DAM SAFETY PROGRAM. SAXTON FALLS DAM (NJ 00277), DELAW--ETC(U)
MAR 79 D J LEARY







































DACW61-78-C-0124


NL

UNCLASSIFIED

1 OF 2

AD
A068675





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD A068675

LEVEL II
DELAWARE RIVER BASIN
MUSCONETCONG RIVER
WARREN COUNTY
NEW JERSEY

DDC
MAY 16 1979

SAXTON FALLS DAM NJ 00277

PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

Approved for public release;
distribution unlimited



DDC FILE COPY

DEPARTMENT OF THE ARMY

Philadelphia District
Corps of Engineers
Philadelphia, Pennsylvania

79 05 14 196
March, 1979

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00277	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Saxton Falls Dam Warren County, N.J.		5. TYPE OF REPORT & PERIOD COVERED ⑨ FINAL / report
7. AUTHOR(s) ⑩ Dennis J. Leary, P.E.		6. PERFORMING ORG. REPORT NUMBER 7
9. PERFORMING ORGANIZATION NAME AND ADDRESS Langan Engineering Assoc. Inc. 970 Clifton Ave. Clifton, N.J. 07013		8. CONTRACT OR GRANT NUMBER(s) ⑪ DACW61-78-C-0124
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, Pennsylvania 19106		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) ⑫ 143p.		12. REPORT DATE ⑪ March 1979
		13. NUMBER OF PAGES 103
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) ⑬ National Dam Safety Program, Saxton Falls Dam (NJ 00277), Delaware River Basin, Musconetcong River, Warren County, New Jersey. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia, 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams Visual Inspection Spillway National Dam Safety Act Report Riprap Saxton Falls Dam Structural Analysis Safety		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report. 410891		



IN REPLY REFER TO:

NAPEN-D

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT CORPS OF ENGINEERS
CUSTOM HOUSE - 220 CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, NJ 08621

9 MAY 1979

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Saxton Falls Dam in Warren County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Saxton Falls Dam, a high hazard potential structure, is judged to be in fair overall condition. The dam's spillway is considered inadequate since 24 percent of the Spillway Design Flood-SDF - would overtop the dam. (The SDF, in this instance, is the Probable Maximum Flood). The decision to consider the spillway "inadequate" instead of "seriously inadequate" is based on the fact that failure from overtopping would not significantly increase the hazard to loss of life downstream from the dam from that which would exist just before overtopping failure. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980. In the interim, a detailed emergency operation plan and warning system, should be promptly developed. Also, during periods of unusually heavy precipitation, around the clock surveillance should be provided.

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the spillway's condition and structural stability (especially the left sidewall). Any remedial measures found necessary should be initiated within calendar year 1980.

This document has been approved
for public release and sale; its
distribution is unlimited.

NOTICE

THIS DOCUMENT HAS BEEN REPRODUCED
FROM THE BEST COPY FURNISHED US BY
THE SPONSORING AGENCY. ALTHOUGH IT
IS RECOGNIZED THAT CERTAIN PORTIONS
ARE ILLEGIBLE, IT IS BEING RELEASED
IN THE INTEREST OF MAKING AVAILABLE
AS MUCH INFORMATION AS POSSIBLE.

NAPEN-D

Honorable Brendan T. Byrne

c. The following remedial actions should be completed within six months from the date of approval of this report:

(1) A trashrack should be installed at the inlet to the gatehouse structure. Suitable hoisting equipment should also be provided.

(2) Erosion at the right and left abutment should be repaired and the area suitably riprapped.

(3) The valve of the 16-inch diameter pipe to the bathing pool should be made functional to increase the low level outlet capacity of the dam.

(4) Spalled and eroded areas on the dam and gatehouse structures should be repaired.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman James A. Courter of the Thirteenth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.


ACCESSION for	
NTIS	White Section <input checked="checked" type="checkbox"/>
DDC	Buff Section <input type="checkbox"/>
UNANNOUNCED	
JUSTIFICATION	
BY	
DATE	
A 23 CP	

NAPEN-D

Honorable Brendan T. Byrne

An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



JAMES G. TGN
Colonel, Corps of Engineers
District Engineer

1 Incl
As stated

Copies furnished:

Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N. J. Dept. of Environmental Protection
P. O. Box CN029
Trenton, NJ 08625

John O'Dowd, Acting Chief
Bureau of Flood Plain Management
Division of Water Resources
N. J. Dept. of Environmental Protection
P. O. Box CN029
Trenton, NJ 08625

SAXTON FALLS DAM (NJ00277)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 6 and 14 December 1978 by Langan Engineering Associates, Inc. under contract to the State of New Jersey. The state, under agreement with the U. S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Saxton Falls Dam, a high hazard potential structure, is judged to be in fair overall condition. The dam's spillway is considered inadequate since 24 percent of the Spillway Design Flood--SDF - would overtop the dam. (The SDF, in this instance, is the Probable Maximum Flood). The decision to consider the spillway "inadequate" instead of "seriously inadequate" is based on the fact that failure from overtopping would not significantly increase the hazard to loss of life downstream from the dam from that which would exist just before overtopping failure. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980. In the interim, a detailed emergency operation plan and warning system, should be promptly developed. Also, during periods of unusually heavy precipitation, around the clock surveillance should be provided.

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the spillway's condition and structural stability (especially the left sidewall). Any remedial measures found necessary should be initiated within calendar year 1980.

c. The following remedial actions should be completed within six months from the date of approval of this report:

(1) A trashrack should be installed at the inlet to the gatehouse structure. Suitable hoisting equipment should also be provided.

(2) Erosion at the right and left abutment should be repaired and the area suitably riprapped.

(3) The valve of the 16-inch diameter pipe to the bathing pool should be made functional to increase the low level outlet capacity of the dam.

(4) Spalled and eroded areas on the dam and gatehouse structures should be repaired.

APPROVED: _____

James G. Ton
JAMES G. TON
Colonel, Corps of Engineers
District Engineer

DATE: _____

9 May 1979

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

NAME OF DAM:	SAXTON FALLS DAM
ID NUMBER:	FED ID NO. 00277
STATE LOCATED:	NEW JERSEY
COUNTY LOCATED:	WARREN
STREAM:	MUSCONETCONG RIVER
RIVER BASIN:	DELAWARE
DATE OF INSPECTION:	DECEMBER 1978


ASSESSMENT OF GENERAL CONDITIONS

Saxton Falls Dam is 50 years old and in fair overall condition. Uncertainties concerning the behavior of the left sidewall and conditions of the spillway and downstream toe areas of the dam lead to the conclusion the dam should be considered to have less than conventional safety margins. The spillway capacity as determined by CE Screening criteria is inadequate. We estimate the dam can adequately pass only 23% of the PMF.

We recommend the crack in the left sidewall be investigated and repaired. The investigation should include borings and be made in such a manner as to provide information leading to an understanding of the cause of the crack and the type of repair and strengthening of the wall that is necessary. This should be done very soon. The present lake level should be lowered below the spillway crest to allow inspection of the downstream dam face, apron and toe area of the dam. This should be done very soon. A trashrack should be installed at the inlet to the gatehouse structure. Suitable hoisting equipment should also be provided. This should be done soon. Erosion at the right and left abutment should be

repaired and the area suitably riprapped. This should be done soon. The valve for the 16-in-dia CI pipe to the bathing pool should be made functional to increase the low level outlet capacity of the dam. This should be done soon. The spalled and eroded areas on the dam and gatehouse structures should be repaired. This should be done in the near future.

The spillway capacity, as determined by CE Screening criteria is inadequate. The actual capacity of the spillway and the SDF should be determined using more precise and sophisticated methods and procedures. The need for and type of mitigating measures should be determined. Around the clock surveillance during periods of unusually heavy precipitation should be provided, and a warning system established. This should be done in the near future.


Dennis J. Leary, P.E.



OVERVIEW
SAXTON FALLS DAM
1 DECEMBER 1978

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

NAME OF DAM:	SAXTON FALLS DAM
ID NUMBER:	FED ID NO. 00277
STATE LOCATED:	NEW JERSEY
COUNTY LOCATED:	WARREN
STREAM:	MUSCONETCONG RIVER
RIVER BASIN:	DELAWARE
DATE OF INSPECTION:	DECEMBER 1978



LANGAN ENGINEERING ASSOCIATES, INC.

Consulting Civil Engineers
990 CLIFTON AVENUE
CLIFTON, NEW JERSEY
201-472-9366

CONTENTS

NATIONAL DAM SAFETY REPORT

SAXTON FALLS DAM FED ID No. NJ00277

	<u>PAGE</u>
PREFACE	
SECTION 1 PROJECT INFORMATION	
1.1 <u>General</u>	1
1.2 <u>Project Description</u>	1
1.3 <u>Pertinent Data</u>	2
SECTION 2 ENGINEERING DATA	
2.1 <u>Introduction</u>	4
2.2 <u>Regional Geology</u>	5
SECTION 3 VISUAL INSPECTION	5
SECTION 4 OPERATIONAL PROCEDURES	6
SECTION 5 HYDRAULIC/HYDROLOGIC	6
SECTION 6 STRUCTURAL STABILITY	7
SECTION 7 ASSESSMENT, RECOMMENDATIONS/ REMEDIAL MEASURES	
7.1 <u>Assessment</u>	7
7.2 <u>Recommendations/Remedial Measures</u>	8
FIGURES	
1. Regional Vicinity Map	
2. Essential Project Features	
3. Regional Geologic Features	
APPENDICES	
1. Check List, Visual Inspection	
2. Photographs	
3. Hydrologic Computations	
4. References	

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

SECTION I PROJECT INFORMATION

1.1 General

Authority to perform the Phase I Safety Inspection of Saxton Falls Dam was received from the State of New Jersey, Department of Environmental Protection, Division of Water Resources by letter dated 20 November 1978. This Authority was given pursuant to the National Dam Inspection Act, Public Law 920-367 and by agreement between the State and the US Army Engineers District, Philadelphia.

The purpose of the Phase I Investigation is to develop an assessment of the general conditions with respect to safety of Saxton Falls Dam and appurtenances based upon available data and visual inspection, and, determine any need for emergency measures and conclude if additional studies, investigations and analyses are necessary and warranted. The assessment is made using screening criteria established in Recommended Guidelines for Safety Inspection of Dams prepared by the Department of Army, Office of the Chief of Engineers. It is not the purpose of the inspection report to imply that a dam meeting or failing to meet the screening criteria, is per se, certainly adequate or inadequate.

1.2 Project Description

Saxton Falls Dam is a 50 year old dam located across the Musconetcong River. Saxton Lake is upstream of the dam. The dam is a 16-ft-high, 235 ft-long reinforced concrete dam having earth-fill abutment at both ends and a gatehouse at the right abutment. A 144-ft-long over-fall type spillway extends along the crest of the dam. A concrete cut-off wall is reported to exist in the right abutment through the filled canal lock and in a small portion of the left abutment immediately adjacent to the abutment wall. A steel sheet piling cut-off is reported to be below the spillway section. The sheeting is reported to have been driven to "refusal" at depths of 15 feet at the right end to 30 feet at the left end. It is reported that the spillway is 11-ft-high from the apron to the crest and has a 24-ft base width and a 5.5-ft top width. The earth-filled right abutment has relatively flat upstream and downstream slopes. The Delaware Lackawanna and Western Railroad situated on an embankment is located at about 35 ft south of the left abutment wall. The outlet works consist of a 4-ft by 6-ft sluice gate operated from the gatehouse and an underground 16-in-dia pipe with control valve which supplies water to a nearby bathing pool fountain. The sluice gate is maintained closed.

A portion of the Morris Canal has been converted into a bathing pool downstream and at the right side of the dam. Water for the bathing pool is supplied through the fountain, which obtains its water from the lake through the underground pipe. A spillway is provided to release excess flow and controls the water level of the bathing pool. At the time of our inspection, the bathing pool was dry.

The dam is located at Mount Olive Township, Morris County, New Jersey. It is at north latitude $40^{\circ} 53.3'$ and west longitude $74^{\circ} 47.9'$. A regional vicinity map is given in Fig 1 and essential features of the dam are given in Fig 2.

Saxton Falls Dam is classified as being "Small" on the basis of its maximum reservoir storage volume of 770 ac-ft which is less than 1000 ac-ft, but more than 50 ac-ft. It is also classified as "Small" on the basis of its total height of 16 ft which is less than 40 feet. The dam is therefore, classified as "Small" in size.

In the National Inventory of Dams, Saxton Falls Dam has been classified as having "High Hazard Potential" on the basis that failure of the dam would cause excessive property damage to residences downstream, and could potentially cause more than a few deaths. Visual inspection of the downstream area shows that breach of the dam would cause damage to residences located immediately adjacent to the river about 800 to 2000 ft from the dam. Accordingly, it is proposed not to change the Hazard Classification Potential.

The owner of the dam is the State of New Jersey, Div. of Forests & Parks, Labor and Industry Bldg. Room 8061, P.O. Box 1420, Trenton, N.J. 08625. The purposes of the dam are flood control and recreation.

The existing dam was built about 80 ft below the location of a former Morris Canal dam that was in bad condition. The Morris Canal was chartered 1824 and opened for traffic 1831. The former dam was erected about 1830 as a feeder for 30.6 miles of the canal between this point and the Delaware River. An average of 34 cfs of water was taken for this purpose. This was drawn from storage in Lake Hopatcong, Cranberry Lake, and Bear Point. This land, including 3.33 miles of right of way, was acquired from Nathaniel Saxton. The new dam included increasing the length of spillway from 111 ft to 144 ft and increasing the height of the dam.

The existing dam was built in 1928 on the left side of a navigation lock for the Morris Canal. Cornelius Vermeule, Consulting and Directing Engineer for the Morris Canal and Banking Company designed the dam and the construction contractor was F.H. Clement and Co.

1.3 Pertinent Data

- | | | |
|----|----------------------------------|-----------------------------|
| a. | Drainage Area is: | 68.0 sq mi |
| | Area of Saxton Lake is: | 63.5 Acres |
| b. | Discharge at Dam site | |
| | Maximum known flood at dam site: | 2295 cfs on 6 February 1896 |

Gated spillway capacity at pool elevation:	292 cfs (4 x 6 sluice gate)
Gated spillway capacity at maximum pool elevation:	356 cfs (4 x 6 sluice gate)
Ungated spillway capacity at maximum pool elevation:	5474 cfs
Total spillway capacity at maximum pool elevation:	5870 cfs (gates opened)
c. Elevation (ft)	
Top dam:	El. 97.55 (End abutments)
Spillway crest:	El. 92.55
Streambed at centerline of dam:	El. 81.5
Maximum tailwater:	Approx. El. 85 at time of inspection (Estimated)
d. Reservoir	
Length of maximum pool:	Approx. 10,000 feet
Length of normal pool:	Approx. 9,500 feet
e. Storage (acre-feet)	
Top of dam:	Approx. 770 AF
Normal pool:	Approx. 400 AF
f. Reservoir Surface (acres)	
Top dam:	86 Acres (estimated)
Maximum pool:	86 Acres (estimated: assumed to be top of dam)
Spillway crest:	63.5 Acres
g. Dam	
Type:	Reinforced concrete with earth embankments at two ends
Length:	235 feet
Height:	11 feet (spillway portion) 16 feet (end embankments portion)

Top width:	5.5 feet (spillway portion) Approx. 40 feet (embankment portion)
Side slopes:	Downstream 1 Hor to 2 Vert, upstream vertical (spillway portion)
Zoning:	None observed
Impervious core:	Unknown
Cutoff:	Reported that sheet pile 15 ft to 30 ft below spillway and concrete cut-off wall at abutments.
Grout curtain:	None observed
h. Spillway	
Type:	Over-fall
Length of weir:	144 feet
Crest elevation:	El. 92.55
U/S Channel:	Musconetcong River
D/S Channel:	Musconetcong River
i. Regulating Outlet	Gatehouse at right abutment with rectangular sluices gate 4 ft wide 6 ft high, opening above El. 83.55

Note: All elevations were obtained from a field survey using a reference elevation of 97.55 at top of south abutment wall (See Fig 2). The reference elevation was obtained from drawings of the Morris Canal & Banking Co., Dover, N.J. office, dated November 20, 1926.

SECTION 2 ENGINEERING DATA

2.1 Introduction

The material observed in the foundation trench through which steel sheet piling was driven to depths of 15 ft to 30 ft below the dam has been described as hard gray sandy hardpan containing numerous boulders from cobbles up to 2 ft. No borings were made for the dam.

There is essentially no available information concerning design and construction of the dam. There is insufficient available information.

Operation consists of maintaining the sluice gate in the gatehouse closed and releasing all water over the spillway.

2.2 Regional Geology

Saxton Falls Dam is located in the New Jersey Highlands physiographic province. The New Jersey Highlands extend across the State in a northeast/southwest direction from the border of New York to the Delaware River and includes the northwest portions of Hunterdon, Passaic, and Morris Counties and the southeastern parts of Warren and Sussex Counties. This province is part of the New England Physiographic Province and lies between the Appalachian Ridge and Valley Province to the northwest and the Piedmont Province to the southeast, see Fig 3.

The Highlands are characterized by rounded and flat-topped northeast/southwest ridges and mountains up to 1,400 ft high separated by narrow valleys. The orientation of the valleys are usually, but not always, controlled by the underlying geologic structure.

Bedrock of the region is predominantly Precambrian gneisses, schists, and metasediments. Some sedimentary strata, typically sandstones, shales and conglomerate have been infolded and infaulted into the valley bottoms.

The regional geologic structure reflects the very old age of bedrock. A number of regional faults cross the area in a northeast southwest direction, including the Ramapo Fault; the more than 30 mile long fault/scarp forms the eastern border of the province. Faults control many of the river valley orientations. The relatively uniform slope of the mountain elevations, from northwest to southeast, is a direct result of the faulting. The entire area is part of the now dissected Schooley Peneplain.

The Pleistocene Age Wisconsin glacier covered all of the dam site area.

The glacier stripped most of the existing overburden and weathered rock and uncovered the numerous hard bedrock knobs and ridges seen throughout the province. Most of the side-slopes in the area are covered with heavy boulder tills (ground moraine), whereas glacial outwash and recent alluvium cover the valleys.

SECTION 3 VISUAL INSPECTION

Saxton Falls Dam is 50 years old and is in generally fair condition. A small amount of erosion, 6-in to 12-in, has occurred at both abutments.

The sidewall at the left abutment of the dam appears to have settled a small amount at its upstream end, resulting in a vertical crack through the entire width of the sidewall approximately seven (7) feet upstream of the dam

face. The width of the crack is approximately 1/2 inch at the top of the wingwall and becomes narrower as it proceeds downwards. It has been repaired recently by a local resident and movement has occurred since its repair.

Deterioration of the concrete near the water surface has exposed the aggregate at the sidewall. In addition, the upstream end of the sidewall has minor spalled areas. The inlet and outlet structures of the outlet works are also spalled in a few areas.

The spillway structure for the bathing pool is spalled in many areas. In one area beneath the concrete walkway over the spillway, the reinforcing steel bars are exposed and heavily rusted.

The sluice gate operator stand appears well maintained and the gate is functional. Observation of the spillway apron and downstream toe was not possible as a result of water flow over the spillway. Our visual check list is given in Appendix 1 and photographs are given in Appendix 2.

SECTION 4 OPERATIONAL PROCEDURES

Operation of the dam is the responsibility of the N.J.D.E.P. Div. of Forests and Parks. Operation consists of keeping the sluice gate closed and releasing water over the spillway. The pipe feeding the bathing pool is no longer used and the valve has been closed. No warning system is in effect.

SECTION 5 HYDRAULIC/HYDROLOGIC

The flood discharge of the river was measured on 6 February 1896 and found to be 2295 cfs. The catchment areas are reported to be:

Above Lake Hopatcong Dam	25.4
Between Hopatcong and Musconetcong Dam	4.9
Free catchment below	37.7
	<u>68.0</u> sq. mi.

The hydraulic/hydrologic evaluation is based on a Spillway Design Flood (SDF) equal to the full Probable Maximum Flood (PMF) chosen in accordance with the evaluation guidelines for dams classified as high hazard and Small in size. Hydrologic design data for this dam is not available. The PMF has been determined by developing a synthetic hydrograph based on the maximum probable precipitation of 22.4 inches (200 square mile - 24 hour). Hydrologic computations are presented in Appendix 3. The PMF peak inflow determined for the subject watershed is 24,141 cfs.

The capacity of the spillway is 5474 cfs which is significantly less than SDF.

Flood routing for the PMF indicates the abutments at both ends will overtop by 6.8 ft. We estimate with gates closed the dam can adequately pass 23% of the PMF.

The downstream potential damage centers are several residential dwellings located immediately adjacent to the river at a distance of 800 to 2000 ft from the dam. Based on our visual inspection of the immediately downstream topography and knowledge of the dam it is our opinion that dam failure resulting from overtopping would cause property damage and would potentially cause more than a few deaths.

Drawdown of the lake below spillway crest has been evaluated assuming the 4 ft by 6 ft sluice gate is functioning properly and is utilized for this purpose. Our calculations indicate the lake level could be lowered 3 ft in approximately 19 hours and 4 ft in about 2 days. We estimate the gate is not capable of lowering the lake by more than 4 feet below the spillway.

SECTION 6 STRUCTURAL STABILITY

Under the conditions at the time of our observations the dam and appurtenances appear stable with the exception of the left spillway sidewall. Our review of available design and construction information also indicate the dam is likely to be stable. The significant post construction condition observed is the cracking and movement of the left sidewall. It is important to note that no engineering data is available concerning the dam foundation and abutment conditions, and evaluation of the condition of the spillway and downstream toe area could not be made because of water flowing over the spillway.

It is our opinion the dam should be considered to have less than conventional safety margins and be potentially unstable under static loading until a) the condition of the dam and downstream toe area can be evaluated with no water flowing over the spillway, and b) the behavior and condition of the left sidewall can be evaluated and corrected.

Saxton Falls Dam is located in Seismic Zone 1 of the Seismic Zone Map of Contiguous States. The static stability of the embankment is considered to be less than conventional safety margins. Therefore, the embankment is considered to be unstable under earthquake loadings.

SECTION 7 ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

7.1 Assessment


Saxton Falls Dam is 50 years old and in fair condition. Uncertainties concerning the behavior of the left sidewall and conditions of the spillway and downstream toe areas of the dam lead to the conclusion the dam should be considered to have less than conventional safety margins.

The spillway capacity as determined by CE Screening criteria is inadequate. We estimate the dam can adequately pass only 23% of the PMF.

7.2 Recommendations/Remedial Measures

We recommend the following measures be taken:

1. The crack in the left sidewall should be investigated and repaired. The investigation should include borings and be made in such a manner as to provide information leading to an understanding of the cause of the crack and the type of repair and strengthening of the wall that is necessary. This should be done very soon.
2. The present lake level should be lowered below the spillway crest to allow inspection of the downstream dam face, apron and toe area of the dam. This should be done very soon.
3. A trashrack should be installed at the inlet to the gatehouse structure. Suitable hoisting equipment should also be provided. This should be done soon.
4. Erosion at the right and left abutment should be repaired and the area suitably riprapped. This should be done soon.
5. The valve for the 16-in-dia CI pipe to the bathing pool should be made functional to increase the low level outlet capacity of the dam. This should be done soon.
6. The spalled and eroded areas on the dam and gatehouse structures should be repaired. This should be done in the near future.
7. The spillway capacity as determined by CE Screening criteria is inadequate. The actual capacity of the spillway and the SDF should be determined using more precise and sophisticated methods and procedures. The need for and type of mitigating measures should be determined. Around the clock surveillance during periods of unusually heavy precipitation should be provided, and a warning system established. This should be done in the near future.




1 in = 5.2 mi

REGIONAL VICINITY MAP
SAXTON FALLS DAM

Fig.1


1

EL. 90.25



2'-0"

EL. 96.0



2


GAGE STATION

97.90



+ 94.63


3



+93.73


+101.60

WILLOW GROVE ST.




4

5




SECTION D-D

SCALE: 1" = 4'



SECTION C-C

SCALE: 1" = 4'



6

+100.55

+106.84

+97.70

93.10

93.20

93.19

97.96

EROSION

97.51

+77.83

START OF EXIST.
LOCK FILLED

B

2' CUT-OFF WALL

C

C

EROSION

96.39 +

71.36

B

PAVED ROAD


16" CIP (24" T)


TOP OF WINGWALL
EL. 90.25

3'


FOUNTAIN

MUSCONETCONG RIVER
EL. 93.20






9



SECTION A-A

SCALE: 1"=6'





10



HEADWALL

75.22


BATHING
POOL

TOP OF GRADE

GATE HOUSE

TOP OF NORTH
CUT-OFF WALL EL. 96.0

MOOVE FOR STOP PLANK




87.69

80.77

+ 81.39

PLAN

SCALE: 1"=20'



12

DATE	DESCRIPTION	NO.
REVISIONS		





13


SECTION B-B

SCALE: 1"=6'

14



ELEVATION
SCALE: 1" = 6'



NOTE:

THE ELEVATIONS SHOWN WERE OBTAINED USING TRANSIT AND LEVEL AND DRAWINGS OF THE MORRIS BANKING CO. DOVER, N.J. OFFICE, NOV. 20, 1926. ELEVATIONS APPROXIMATE. THE BENCHMARK ELEVATION OF 97.5' ABUTMENT WALL WAS USED AS SHOWN ON SAID DRAWINGS. SHOWN BELOW GROUND SURFACE AND WATER LEVEL ON THE BASIS OF THE ABOVE MENTIONED DWGS.

LANGAN ENGINEERING ASSOCIATES, INC.

990 Clifton Avenue, Clifton, New Jersey 07013
(201) 472-9366

PROJECT

PHASE I
INSPECTION & EVALUATION
NEW JERSEY DAMS

DRAWING TITLE

SAXTON FALLS DAM
JANUARY 1979
FED. I.D. NO. NJ00277

JOB NO.

J - 783B

DATE

25 FEB 1979

SCALE

AS NOTED

DRN. BY

J. R.


CHKD. BY

D. J. L.

DRAWING NO.

FIG. 2

ED USING A SURVEYOR'S
E MORRIS CANAL &
926. ELEVATIONS ARE
OF 97.55 ON THE SOUTH
SAID DWGS. INFORMATION
ER LEVEL ARE INFERRED
DWGS.



Schematic Cross-section
New Jersey Highlands
Physiographic Province
(After Wolfe, 1977)

REGIONAL GEOLOGIC FEATURES

Fig. 3

APPENDIX I

CHECK LIST
VISUAL INSPECTION

SAXTON FALLS DAM

CHECK LIST VISUAL INSPECTION

Phase I

NAME DAM Saxton Falls Dam COUNTY Morris STATE New Jersey COORDINATORS N.J. DEP

DATE(s) INSPECTION See below WEATHER Clear TEMPERATURE 40° F

POOL ELEVATION AT TIME OF INSPECTION 93.20 TAILWATER AT TIME OF INSPECTION 85.0+

*Elevations are referenced to a BM elevation of 97.55 at top of south abutment wall (see Fig. 2)

INSPECTION PERSONNEL:

<u>D. Leary (12/6/78)</u>	<u>P. Yu (12/14/78)</u>
<u>J. Richards (12/6/78)</u>	<u>C. Campbell (12/14/78)</u>
<u>J. Rizzo (12/14/78)</u>	

James L. Richards RECORDER

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Dead trees and rubber tires in channel.	Trees and tires should be removed.
SLOPES	Erosion about 5 to 10 ft. along right downstream slope approximately 200 ft. below dam.	Eroded areas should be repaired.
APPROXIMATE NO. OF HOMES AND POPULATION	5 homes located immediately downstream. Greater than 25 people estimated. Homes located 5 to 10 ft. below spillway crest.	

EARTH EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SEE PAGE ON LEAKAGE		
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	Erosion two to three inches deep at downstream right abutment/structure junction. Erosion at downstream of left abutment/structure junction.	Eroded areas should be repaired.
DRAINS	Appears satisfactory.	
WATER PASSAGES	Spotted areas of debris.	Debris should be removed.
FOUNDATION (Direction: looking d/s)	Not observable.	

CONCRETE/MASONRY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	Concrete on both abutments has cracks on three sides.	Cracks should be repaired.
STRUCTURAL CRACKING	Crack above and below downstream gatehouse wall. Steel beam rusted.	
VERTICAL AND HORIZONTAL ALIGNMENT	Appears satisfactory.	
MONOLITH JOINTS	Not observed.	
CONSTRUCTION JOINTS		

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Appears satisfactory.	
INTAKE STRUCTURE	Cracks along top and sides.	Concrete cracks should be repaired.
OUTLET STRUCTURE	Top of concrete outlet walls spalled on downstream side.	Spalled concrete should be repaired.
OUTLET CHANNEL	Leaves, bottles, pieces of spalled concrete from walls, and paper in channel.	Debris should be removed.
EMERGENCY GATE	None observed.	

RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARK OR RECOMMENDATIONS
SLOPES	Sides have eroded in several locations.	
SEDIMENTATION	Appears satisfactory.	

UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Dead logs and leaves have accumulated.	Debris should be removed.
APPROACH CHANNEL	Dead trees and stumps in channel. Sediment behind spillway wall to height of spillway.	Debris and sediment should be removed.
DISCHARGE CHANNEL	A dilapidated boat, dead trees, brush and wood in channel.	Boat and debris should be removed.
BRIDGE AND PIERS		

INSTRUMENTATION

VISUAL EXAMINATION	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	None observed.	
OBSERVATION WELLS	None observed.	
WEIRS		
PIEZOMETERS		
OTHER	Water depth gage attached to inlet wall has algae growth below 1.40.	

GATE HOUSE

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	Two areas of approximately 2 ft square have spalled concrete. Several cracks across top, and down sides.	Spalled areas should be repaired. Cracked concrete should be further investigated.
APPROACH CHANNEL	Bottle, leaves and dead trees in channel.	Debris should be removed.
DISCHARGE CHANNEL	Concrete spalled and several surface cracks.	Spalled concrete areas should be repaired.
BRIDGE AND PIERS		
GATES AND OPERATION EQUIPMENT	Crank type operator located in center of gatehouse, rusted. However, it appears to be functional.	

APPENDIX 2

PHOTOGRAPHS

SAXTON FALLS DAM



Spillway and Discharge Channel.
Looking Upstream.


6 December 1978



Spillway. Looking south.


6 December 1978

SAXTON FALLS DAM



Top of spillway and riprapped.
Left bank of discharge channel.

6 December 1978




Gatehouse at right side of spillway.

6 December 1978




Gatehouse and spillway. Looking upstream. 6 December 1978




Erosion at right abutment immediately north of gate house. 6 December 1978


SAXTON FALLS DAM



Discharge opening of downstream side of gate house. 6 December 1978



Spalled concrete on south wall of gate house discharge channel. 6 December 1978




Water level gage at gate house.

6 December 1978



Former lock and valve chamber used
to release water into lake for swimming.

6 December 1978



Left sidewall of spillway.

6 December 1978



Spalling of concrete at left side wall
of spillway.

6 December 1978

SAXTON FALLS DAM



Recently repaired crack in left
sidewall of spillway.

6 December 1978



Erosion at abutment of left sidewall
of spillway.

6 December 1978

APPENDIX 3

HYDROLOGIC COMPUTATIONS

SAXTON FALLS DAM

HYDROLOGIC COMPUTATIONS

SAXTON FALLS DAM

Location: Morris - Warren County, N.J.

Drainage Area: 68 sq. mi - $\left\{ \begin{array}{l} 25.4 \text{ sq. mi to Lake Hopatcong} \\ 4.9 \text{ sq. mi to Lake Musconetcong proper} \\ 37.7 \text{ sq. mi to Saxton Falls proper} \end{array} \right.$

Lake Area: 63.5 Ac.

Classification: size - small
hazard - high

Spillway Design Flood

Based on available information, it is understood that the spillway has been designed on the basis of the flood data obtained on Feb. 6, 1896.

In accordance with the evaluation criteria, $\frac{1}{2}$ PMF to PMF should be used and PMF is chosen.

COMPUTE PMF

1. Dam located in Zone 6

PMP = 22.4 inches (200 sq. mi in 24 hrs)

2. PMF must be adjusted for basin size

<u>Duration - hr.</u>	<u>% Factor (for 200 sq. mi)</u>	<u>Reduction Factor^x</u>
0-6	100	
0-12	109	
0-24	119	0.835
0-48	131	
		$\times \text{P.M.F. 'D.S.D.'}$

3. Methodology

- a) PMF be calculated using HEC-1 with Snyder Coefficients $C_e = 3.70$ and $C_p = 0.58$ recommended by the Army Corp of Engineers.
- b) Within Saxton Falls drainage basin lie Lakes Hopatcong and Musconetcong. The outflow hydrograph of Lake Hopatcong is combined with the local inflow of Lake Musconetcong and routed to obtain the outflow hydrograph of Lake Musconetcong. This outflow hydrograph of Lake Musconetcong is routed through 2 reaches to upstream end of Saxton Lake. Such routed hydrograph is added to the local inflow of Saxton Lake which in turn yields the inflow hydrograph for Saxton Falls Dam. The procedure is illustrated on a schematic network shown on sheet No. 3
- c) Considering the valley topography of the Musconetcong River between Lake Musconetcong and Saxton Lake, a generalized channel section is used at each reach for the channel routing. The generalized channel sections are shown on sheet No. 4

BY

Py

DATE 2-3-79

Saxton Falls Dam

JOB NO.

J-7858

CKD

CED


DATE 3-28-79

SHEET NO.

2


OF 13

Catchment Basin



- ① - Hopatcong Subbasin
- ② - Musconetcong Subbasin
- ③ - Saxton Subbasin
- 1 to 6 - Reach numbers

Schematic Network




GENERALIZED CHANNEL SECTION

Reach 4: Left & right overbank Manning's $n = 0.06$

Channel Manning's $n = 0.04$


Channel slope (from Lake Musconetcong to reach 4)
 $\doteq 0.0146$



Reach 5: Left & right overbank Manning's $n = 0.06$

Channel Manning's $n = 0.04$

Channel slope (reach 4 to reach 5)
 $= 0.0013$



Note: Channel section generated by assumption for main channel dimensions and information from U.S.G.S. Topographic maps.
 Numbers in brackets are coordinates used for defining the sections.

BY DJ
 CKD GED

DATE 2-1-79
 DATE 3-28-79

Santon Falls Dam

JOB NO. T-7858

SHEET NO. 4 OF 13

UNIT HYDROGRAPH

Corp of Engineers has indicated that Snyder Method be used to develop local inflow for Saxton Falls' intermediate drainage area.

$$C_t = 3.7, C_p = 0.58$$

Snyder lag time:

$$t_p = C_t (L \cdot L_{ca})^{0.3}$$

from drainage area


$$L = 80000 \text{ ft} = 15.2 \text{ mi}$$

$$L_{ca} = 28000 \text{ ft} = 5.3 \text{ mi}$$

$$\therefore t_p = 3.7 (15.2 \times 5.3)^{0.3}$$



$$= \underline{13.8 \text{ hrs}}$$

$$\underline{C_p = 0.58}$$



Saxton Lake Subbasin

SPILLWAY CAPACITY



$$Q = CLH^{3/2}$$

Spillway section resembles trapezoidal cross-section with vertical upstream face, inclined downstream face and rounded corners. Choose $C_{avg} = 3.4$ (Ref. Table 5-9 of 'Handbook of Hydraulics' by King & Brater)
 $L = 144'$

End abutments are of irregular shape.

Take effective length of 90 feet (both ends)


$$C_{avg} = 2.7$$

Elev. (ft)	Spillway		End Abutments		$Q_T(cfs)$ $= Q_S + Q_E$
	H(ft)	$Q_S(cfs)$	H(ft)	$Q_E(cfs)$	
92.55	0				0
93.55	1	490			490
94.55	2	1385			1385
95.55	3	2544			2544
96.55	4	3917			3917
97.55	5	5474	0		5474
98.55	6	7196	1	243	7439
99.55	7	9068	2	687	9755
100.55	8	11078	3	1263	12341
101.55	9	13219	4	1944	15163
102.55	10	15483	5	2717	18200
103.55	11	17862	6	3571	21433
104.55	12	20352	7	4500	24852
105.55	13	22949	8	5498	28447

Top of
dam

$$Q_S = 489.6 H^{3/2}$$

$$Q_E = 243 H^{3/2}$$



BY <u>Dry</u>	DATE <u>2-3-79</u>	<u>Sexton Falls Dam</u>	JOB NO. <u>J-7638</u>
CKD <u>GED</u>	DATE <u>3-28-79</u>		SHEET NO. <u>8</u> OF <u>13</u>

Reservoir Storage Capacity

Assume a linear distribution for the area of the lake with elevation. Start at a zero storage at the crest of the spillway.

Area of Lake = 63.5 Acres

Perimeter of Lake = 32500 ft (measured from U.S.G.S. map)

Since perimeter is estimated from U.S.G.S. map, \therefore for estimated analysis purpose, it is assumed to be constant within the working elevation range.

Take average side slope = 1V : 6H.

\therefore for every foot of water above the crest of spillway, the area of lake increases by $\frac{6(32500)}{43560} = 4.5$ Ac.

Elev. (ft)	(ft)	Increase in Lake area (Acres)	Area of Lake (Acres)
92.55	0		63.5
93.55	1	4.5	68.0
94.55	2	9.0	72.5
95.55	3	13.5	77.0
96.55	4	18.0	81.5
97.55	5	22.5	86.0
98.55	6	27.0	90.5
99.55	7	31.5	95.0
100.55	8	36.0	99.5
101.55	9	40.5	104.0
102.55	10	45.0	108.5
103.55	11	49.5	113.0
104.55	12	54.0	117.5
105.55	13	58.5	122.0


BY <u>PR</u>	DATE <u>2-3-79</u>	<u>Simon F. J. Dan</u>	JOB NO. <u>J-78313</u>
CKDGED	DATE <u>3-28-79</u>		SHEET NO. <u>9</u> OF <u>13</u>

SUMMARY OF HYDROGRAPH AND FLOOD ROUTING

1. Hydrograph and routing calculated using HEC-1
2. PMF for Saxton Lake is 24141 cfs (routed to 24135 cfs)
3. Routing indicates the dam (and abutments) overtops by approx. 6.8 ft for PMF

OVERTOPPING POTENTIAL

1. Various % of PMF have been routed using HEC-1
2. Plot peak outflow vs % PMF



3. Dam overtops at approx. El. 97-55 with $Q = 5474$ cfs.
 i.e. dam can pass approx. 23% of PMF

BY <u>Phy</u>	DATE <u>2-7-79</u>	<u>Saxton Falls Dam</u>	JOB NO. <u>J-7638</u>
CKD <u>GED</u>	DATE <u>3-28-79</u>		SHEET NO. <u>10</u> OF <u>13</u>

DRAWDOWN ANALYSIS

1. Outlet structures

1 - 4' x 6' sluiceway

(outlet for 16" pipe appeared blocked, \therefore not considered)

2. Outlet Capacity

Sill of gate at El. 83.55

top of gate at El. 89.55

When pool elevation is above El. 89.55, gate discharge is governed by orifice flow. As pool elevation is lowered below El. 89.55, gate discharge is governed by weir flow. Use $C = 3.0$ for weir flow and $C = 0.62$ for orifice flow

	Elev. (ft)	Head (ft)	Q (cfs)	Q _{out avg.} (cfs)
orifice flow ↑	92.55	6	292	280
	91.55	5	267	253
	90.55	4	239	208
	89.55	6	176	155
weir flow ↓	88.55	5	134	115
	87.55	4	96	79
	86.55	3	62	48
	85.55	2	34	23
	84.55	1	12	6
	83.55	0	0	

BY Py DATE 2-5-79 Canton Falls Dam

JOB NO. 5-7838

CKD GED DATE 3-28-79

SHEET NO. 11 OF 13

3. Storage Capacity

a. Estimated storage above lowest elevation of the gate is 350 ac-ft

b. Assume area varies linearly with height.
Area of lake at bottom of gate = 14.3

Elev. (ft)	Area (Ac)	Δ Storage (Ac-ft)	Total Storage (Ac-ft)
92.55	63.5	60.75	350
91.55	58.0	55.3	
90.55	52.6	49.85	
89.55	47.1	44.35	
88.55	41.6	38.9	
87.55	36.2	33.45	
86.55	30.7	27.95	
85.55	25.2	22.5	
84.55	19.8	17.05	
83.55	14.3		

4. Assume inflow to be 2 cfs/sq. mi

$$Q_{in} = 2 \times 68 = 136 \text{ cfs.}$$

Elev. (ft)	$Q_{out \text{ avg.}}$ (cfs)	Q_{net}^* (cfs)	$\Delta \text{Storage}$ (Ac-ft)	Δt (hr.)	$\Sigma \Delta t$ (hr.)
92.55	280	144	60.75	5.1	
91.55	253	117	55.3	5.7	
90.55	208	72	49.85	8.4	19.2
89.55	155	19	44.35	28.2	47.4 (1.98 days)
88.55	115	-**	38.9		
87.55	79	-	33.45		
86.55	48	-	27.95		
85.55	23	-	22.5		
84.55	6	-	17.05		
83.55					


* $Q_{net} = Q_{out \text{ avg.}} - Q_{in} = Q_{out \text{ avg.}} - 136$


** $Q_{in} > Q_{out}$ not considered

First 3 feet of lake can be lowered in about 19 hrs.

Lake can be lowered 4 feet in approximately 2 days.


We estimate the gate is not capable of lowering the lake more than 4 feet.


















































HEC-1 OUTPUT

SAXTON FALLS DAM

.....
 FLOOD HYDROGRAPH PACKAGE (MEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 11 JAN 79

SAXTON FALLS DAM INFLOW HYDROGRAPH AND ROUTING N.J. DAM INSPECTION		HOPATCONG LOCAL		HOPATCONG		MUSCONETCONG LOCAL		MUSCONETCONG	
1	2	3	4	5	6	7	8	9	10
1	200	1	0	0	0	0	0	0	0
2	3	1	0	0	0	0	0	0	0
3		1	0	0	0	0	0	0	0
4		1	0	0	0	0	0	0	0
5		1	0	0	0	0	0	0	0
6		1	0	0	0	0	0	0	0
7		1	0	0	0	0	0	0	0
8		1	0	0	0	0	0	0	0
9		1	0	0	0	0	0	0	0
10		1	0	0	0	0	0	0	0
11		1	0	0	0	0	0	0	0
12		1	0	0	0	0	0	0	0
13		1	0	0	0	0	0	0	0
14		1	0	0	0	0	0	0	0
15		1	0	0	0	0	0	0	0
16		1	0	0	0	0	0	0	0
17		1	0	0	0	0	0	0	0
18		1	0	0	0	0	0	0	0
19		1	0	0	0	0	0	0	0
20		1	0	0	0	0	0	0	0
21		1	0	0	0	0	0	0	0
22		1	0	0	0	0	0	0	0
23		1	0	0	0	0	0	0	0
24		1	0	0	0	0	0	0	0
25		1	0	0	0	0	0	0	0
26		1	0	0	0	0	0	0	0
27		1	0	0	0	0	0	0	0
28		1	0	0	0	0	0	0	0
29		1	0	0	0	0	0	0	0
30		1	0	0	0	0	0	0	0
31		1	0	0	0	0	0	0	0
32		1	0	0	0	0	0	0	0
33		1	0	0	0	0	0	0	0
34		1	0	0	0	0	0	0	0
35		1	0	0	0	0	0	0	0
36		1	0	0	0	0	0	0	0
37		1	0	0	0	0	0	0	0
38		1	0	0	0	0	0	0	0
39		1	0	0	0	0	0	0	0
40		1	0	0	0	0	0	0	0
41		1	0	0	0	0	0	0	0
42		1	0	0	0	0	0	0	0
43		1	0	0	0	0	0	0	0
44		1	0	0	0	0	0	0	0
45		1	0	0	0	0	0	0	0
46		1	0	0	0	0	0	0	0
47		1	0	0	0	0	0	0	0
48		1	0	0	0	0	0	0	0
49		1	0	0	0	0	0	0	0
50		1	0	0	0	0	0	0	0

[illegible]

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

```

RUNOFF HYDROGRAPH AT
ROUTE HYDROGRAPH AT
ROUTE HYDROGRAPH AT
CONJUNE 2 HYDROGRAPHS AT
ROUTE HYDROGRAPH TO
ROUTE HYDROGRAPH TO
ROUTE HYDROGRAPH TO
RUNOFF HYDROGRAPH AT
CONJUNE 2 HYDROGRAPHS AT
ROUTE HYDROGRAPH TO
END OF NETWORK

```


AD-A068 675


NEW JERSEY STATE DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/G 13/2
NATIONAL DAM SAFETY PROGRAM. SAXTON FALLS DAM (NJ 00277); DELAW--ETC(U)
MAR 79 D J LEARY DACW61-78-C-0124

UNCLASSIFIED


NL

2 OF 2

AD
A068675



END
DATE
FILMED
6-79
DDC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

 -LOAD HYDROGRAPH PACKAGE (REC-1)
 JAN SAFETY VERSION JULY 1978
 LAST MODIFICATION 11 JAN 79

NOV DATE# 79/03/20.
 TIME# 11.27.15.

SAXTON FALLS DAM
 INFLOW HYDROGRAPH AND ROUTING
 N.J. DAM INSPECTION

NO 200 NHR 1 NMIN 0 IDAY 0 JOPER 3
 JOB SPECIFICATION
 IHR 0 IMIN 0 METRC 0
 MWI 0 LROPI 0 TRACE 0
 IPLT 0 IPRI 0 NSTAN 0

***** SUB-AREA RUNOFF COMPUTATION *****

COMPUTE HYDROGRAPH - HOPATCONG LOCAL
 SUB-AREA RUNOFF COMPUTATION

ISTAQ 1 ICOMP 0 IECON 0 ITAPE 0 JPLT 0 JPR1 0 INAME 1 ISTAGE 0 IAUTO 0

HYDROGRAPH DATA
 IHYDG 1 TUNG 1 TAREA 25.40 SNAP 0.00 TRSDA .82 TRSPC 0.000 RATIO 0.000 ISAME 0 LOCAL 0

PRECIP DATA
 SPFF 0.00 PMS 22.40 R6 104.00 R12 113.00 R24 123.00 P48 135.00 R96 0.00

LOSS DATA
 LROPI 1 STKRS 0.00 RLTKR 0.00 RTIOL 1.00 ERAIN 0.00 STKRS 0.00 RTIOL 1.00 SIRT 1.00 CNSTL .15 ALSMX 5.00 RIIMP 0.00

UNIT HYDROGRAPH DATA
 TP= 12.00 CP= .58 NIA= 0

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC=12.9R AND R=12.7R INTERVALS
 RECESSION DATA
 STKRS=-2.00 ORCSN=0.00 RTIOR=1.00
 SIRT=1.00

UNIT HYDROGRAPH 75 END-OF-PERIOD ORIGINATES, LAGE= 12.03 HOURS, CP= .58 VOL=1.00
 19: 70: 123: 424: 624: 701: 760:
 442: 108: 323: 539: 599: 717: 760:
 202: 168: 147: 298: 253: 317: 478:
 32: 79: 67: 136: 117: 108: 218:
 42: 39: 31: 62: 46: 108: 45:
 19: 16: 14: 28: 26: 22: 21:
 9: 17: 6: 13: 12: 10: 9:

MO.DA HR.MN PERIOD RAIN EXCS LOSS END-OF-PERIOD FLOW MO.DA HR.MN PERIOD RAIN EXCS LOSS COMP 0
 1. 1. 1 .61 0.0 0.1 1.05 5.00 101 0.00 0.00 1.01 0.00 0.00 0.00

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

[illegible]

POLYMER LETTERS

[illegible][illegible]

555555666666777778888999000011111

[illegible][illegible]

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....

.....
.....
.....

.....
.....
.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

[illegible][illegible][illegible][illegible]

အထွေထွေအချက်အလက်များကို အောက်ဖော်ပြပါအတိုင်း ဖော်ပြထားပါသည်။

[illegible][illegible]

QLOSS	ICOMP	IECON	ROUTING DATA	JPLT	JPRI	INAME	ISTAGE	IAUTO
0.00	1	0	0	0	0	1	0	0
CLOSS	AVG	RES	ISAME	IOPT	IPMP		LSTR	
0.000	0.00	1	0	0	0			
NSTPL	NSTDL	LAG	AMSCK	X	YSK	STORA	ISPRAT	
1	0	0	0.000	0.000	0.000	0.	0	

JOURNAL DEPTH CHANNEL ROUTING

QNC(1)	.0600	ELNVT	627.0	ELMAX	650.0	RLNTH	14000.	SEL	.00150
--------	-------	-------	-------	-------	-------	-------	--------	-----	--------

CROSS SECTION COORDINATES--STA,FLEV,STA,ELEV--ETC
L.OJ 651.00 100.00 650.00 1510.00 635.00
1598.00 635.00 1670.00 640.00 1945.00 651.00

SURAGE		0.00	89.11	19799	35.63	55.04	78.22	105.17	130.56	216.86	345.97
		522.88	759.14	1047.49	1391.28	1791.12	2247.01	2785.94	3322.91	3950.93	4630.99
OUTFLOW		0.00	33.33	120.31	267.84	485.02	780.30	1164.23	1693.38	2538.18	3598.45
		5364.92	7664.32	10631.60	14401.46	19082.28	24742.22	31469.12	39343.03	48441.64	58336.60
STAGE		637.00	628.21	629.42	630.63	631.84	633.05	634.26	635.47	636.68	637.89
		639.11	640.32	641.53	642.74	643.95	645.16	646.37	647.58	648.79	650.00
FLOW		1.00	33.33	120.31	267.84	485.02	780.30	1164.23	1693.38	2538.18	3598.45
		5364.92	7664.32	10631.60	14401.46	19082.28	24742.22	31469.12	39343.03	48441.64	58336.60

[illegible]

[illegible]

.....

315.
3308
2977
261
267
2323
2306
1922
1466
1180
1175
1159
1134
1150
146
42
1138
1132
1132
1128
1125
1121
1116
1111
1112
1110
1108
106
103
111
97
97
95
94
92
91
89
88
87
85
84
82
81
80
79
78
77
76
75
73
72
71
70
69
68
67

[illegible][illegible][illegible]

.....

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000 1001 1002 1003 1004 1005 1006 1007 1008 1009 1010 1011 1012 1013 1014 1015 1016 1017 1018 1019 1020 1021 1022 1023 1024 1025 1026 1027 1028 1029 1030 1031 1032 1033 1034 1035 1036 1037 1038 1039 104

012470
65903
55874
55657
55591
55412
55324
55167
55099
4991
4768
4692
4525
4370
4216
4092
3958
3882
3769
3664
3559

612
610
609
608
607
606
605
604
603
602
601
600
599
598
597
596
595
594
593
592
591
590
589
588
587
586
585
584
583
582
581
580
579
578
577
576
575
574
573
572
571
570
569
568
567
566
565
564
563
562
561
560
559
558
557
556
555
554
553
552
551
550
549
548
547
546
545
544
543
542
541
540
539
538
537
536
535
534
533
532
531
530
529
528
527
526
525
524
523
522
521
520
519
518
517
516
515
514
513
512
511
510
509
508
507
506
505
504
503
502
501
500
499
498
497
496
495
494
493
492
491
490
489
488
487
486
485
484
483
482
481
480
479
478
477
476
475
474
473
472
471
470
469
468
467
466
465
464
463
462
461
460
459
458
457
456
455
454
453
452
451
450
449
448
447
446
445
444
443
442
441
440
439
438
437
436
435
434
433
432
431
430
429
428
427
426
425
424
423
422
421
420
419
418
417
416
415
414
413
412
411
410
409
408
407
406
405
404
403
402
401
400
399
398
397
396
395
394
393
392
391
390
389
388
387
386
385
384
383
382
381
380
379
378
377
376
375
374
373
372
371
370
369
368
367
366
365
364
363
362
361
360
359
358
357
356
355
354
353
352
351
350
349
348
347
346
345
344
343
342
341
340
339
338
337
336
335
334
333
332
331
330
329
328
327
326
325
324
323
322
321
320
319
318
317
316
315
314
313
312
311
310
309
308
307
306
305
304
303
302
301
300
299
298
297
296
295
294
293
292
291
290
289
288
287
286
285
284
283
282
281
280
279
278
277
276
275
274
273
272
271
270
269
268
267
266
265
264
263
262
261
260
259
258
257
256
255
254
253
252
251
250
249
248
247
246
245
244
243
242
241
240
239
238
237
236
235
234
233
232
231
230
229
228
227
226
225
224
223
222
221
220
219
218
217
216
215
214
213
212
211
210
209
208
207
206
205
204
203
202
201
200
199
198
197
196
195
194
193
192
191
190
189
188
187
186
185
184
183
182
181
180
179
178
177
176
175
174
173
172
171
170
169
168
167
166
165
164
163
162
161
160
159
158
157
156
155
154
153
152
151
150
149
148
147
146
145
144
143
142
141
140
139
138
137
136
135
134
133
132
131
130
129
128
127
126
125
124
123
122
121
120
119
118
117
116
115
114
113
112
111
110
109
108
107
106
105
104
103
102
101
100
99
98
97
96
95
94
93
92
91
90
89
88
87
86
85
84
83
82
81
80
79
78
77
76
75
74
73
72
71
70
69
68
67
66
65
64
63
62
61
60
59
58
57
56
55
54
53
52
51
50
49
48
47
46
45
44
43
42
41
40
39
38
37
36
35
34
33
32
31
30
29
28
27
26
25
24
23
22
21
20
19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1
0

.....

[illegible][illegible][illegible]

363126.	TOTAL VOLUME
10452.49)	369947.
	10447.
	18.88
	479.51
	30491.
	37611.

SUM	72-HOUR
4092.	116.
15.07	382.89
34348.	24033.
30033.	

24-HOUR
5513.
1567
1716.95
10934.
13487.

5-HOUR
5892
167
181
4594
2922
3604

PEAK:
925:
169:

CFS
 CMSS
 INCHES
 AC-FT
 THOUS CU FT

MAXIMUM STAGE IS	639.4
------------------	-------

.....

.....

.....

.....

SUB-AREA RUNOFF COMPUTATION

COMPUTER HYDROGRAPH - SAYTON LAKE LOCAL

INSTAG	ICOMP	IECON	ITYPE	JPLT	JPRJ	INAME	ISSTAGE	IAUTO
5	0	0	0	F	0	1	0	0

IUNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	TSNOW	TSAME	LOCAL
1	17-76	0-00	17-75	-84	0.009	0	0	0

HYDROGRAPH DATA

ALAN D. JONES

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

.....
.....
.....

୧୨୩୪୫୬୭୮୯୧୦୧୧୧୨୧୩୧୪୧୫୧୬୧୭୧୮୧୯୨୦
 ୨୧୨୨୨୩୨୪୨୫୨୬୨୭୨୮୨୯୩୦୩୧୩୨୩୩୩୪୩୫
 ୩୬୩୭୩୮୩୯୪୦୪୧୪୨୪୩୪୪୪୫୪୬୪୭୪୮୪୯୫୦

722
721
710
709
699
698
697
696
695
694
693
692
691
690
689

[illegible]

681368035814770471594
55545221099877655433
5555555544444444444444

0000000000000000000000
0000000000000000000000
.
12345678901234567890

3333333333333333333333

PEAK OUTFLOW IS 24135. AT TIME 53.00 HOURS

VOLUME
855197.
24216.
19.50
495.26
70677.
87179.

72-HOUR
10413.
295.
17.09
434.19
61963.
76430.

24-HOUR
18793.
532.28
10.19
261.19
37275.
45978.

6-HOUR
23447.
664.1
3.217
81.47.
11627.
14341.

PEAK
24135.
683.

CFS
CHS
INCHES
AC-FT
THOUS CU M

◆◆◆◆◆

•
•
•
•
•
•
•
•
•
•

●●●●●●●●●●

•
•
•
•
•
•
•
•
•

.....

RUNOFF SUMMARY, AVERAGE FLOW IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

HYDROGRAPH AT		PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
1	(15026.	14418.	10167.	4450.	25.40
		425.48)(404.27)(287.88)(126.02)(65.79)
ROUTED TO						
2	(5640.	5600.	5103.	3406.	25.40
		159.70)(158.56)(144.51)(96.45)(65.79)
HYDROGRAPH AT						
2	(5580.	4978.	2530.	912.	4.90
		158.01)(140.97)(71.63)(25.82)(12.59)
2-COMBINED						
2	(6140.	5947.	5603.	4117.	30.30
		173.86)(168.40)(158.66)(117.14)(78.48)
ROUTED TO						
3	(5948.	5914.	5518.	4099.	30.30
		168.42)(167.47)(156.25)(116.07)(78.48)
ROUTED TO						
4	(5945.	5909.	5517.	4095.	30.30
		168.35)(167.31)(156.23)(115.97)(78.48)
ROUTED TO						
5	(5925.	5892.	5513.	4092.	30.30
		167.77)(166.84)(156.10)(115.87)(78.48)
HYDROGRAPH AT						
5	(19182.	18574.	13462.	6428.	37.70
		543.18)(525.96)(392.52)(182.33)(97.64)
2-COMBINED						
5	(24141.	23482.	18804.	10417.	68.00
		683.60)(664.92)(532.48)(294.39)(176.12)
ROUTED TO						
6	(24135.	23447.	18793.	10413.	68.00
		683.43)(663.95)(532.15)(294.27)(176.12)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 923.30 0. 0.	SPILLWAY CREST 923.30 0. 0.	TOP OF DAM 927.70 11050. 3073.	
	RATIO OF PMF 0.00	MAXIMUM RESERVOIR W.S.-ELEV 929.34	MAXIMUM STORAGE AC-FT 15245.	MAXIMUM OUTFLOW CFS 5640.	DURATION OVER TOP HOURS 37.00
		MAXIMUM DEPTH OVER DAM 1.64		TIME OF MAX OUTFLOW HOURS 65.00	TIME OF FAILURE HOURS 0.00

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 859.75 0. 0.	SPILLWAY CREST 859.75 0. 0.	TOP OF DAM 863.50 1172. 3460.	
	RATIO OF PMF 0.00	MAXIMUM RESERVOIR W.S.-ELEV 865.34	MAXIMUM STORAGE AC-FT 1761.	MAXIMUM OUTFLOW CFS 5348.	DURATION OVER TOP HOURS 46.00
		MAXIMUM DEPTH OVER DAM 1.84		TIME OF MAX OUTFLOW HOURS 65.00	TIME OF FAILURE HOURS 0.00

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 92.55 0. 0.	SPILLWAY CREST 92.55 0. 0.	TOP OF DAM 97.55 374. 5474.	
	RATIO OF PMF 0.00	MAXIMUM RESERVOIR W.S.-ELEV 104.54	MAXIMUM STORAGE AC-FT 1061.	MAXIMUM OUTFLOW CFS 24135.	DURATION OVER TOP HOURS 48.00
		MAXIMUM DEPTH OVER DAM 6.79		TIME OF MAX OUTFLOW HOURS 53.00	TIME OF FAILURE HOURS 0.00

.....
FLOOD HYDROGRAPH PACKAGE (HEC-1)
DAM SAFETY VERSION JULY 1978
LAST MODIFICATION 11 JAN 79
.....

.....FLOOD HYDROGRAPH PACKAGE (HEC-1)
 JAM SAFETY VERSION JULY 1976
 LAST MODIFICATION 11 JAN 79

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT	1
ROUTE HYDROGRAPH TO	2
RUNOFF HYDROGRAPH AT	2
COMBINE 2 HYDROGRAPHS AT	2
ROUTE HYDROGRAPH TO	3
ROUTE HYDROGRAPH TO	4
RUNOFF HYDROGRAPH AT	5
COMBINE 2 HYDROGRAPHS AT	5
ROUTE HYDROGRAPH TO	6
END OF NETWORK	

42

SAXTON FALLS DAM
Z PMF
W. J. DAM INSPECTION

```

JOB SPECIFICATION
=====
N=4R      NMIN 0      IDAY 0      IPRY 4      INSTAN 0
N=00      NMAX 0      JORE 5      IPLY 0      METRC 0
N=00      NWT 0      LROPY 0      TRACE 0
=====

```

MULTI-PLAN ANALYSES TO BE PERFORMED
NPLAN= 1 NRYIO= 6 LRIO= 1
.50 .40 .30 .20 .10

.....

.....

.....

.....

.....

SUB-AREA KUNOFF COMPUTATION
COMPUTE HYDROGRAPH - HOPATCONG LOCAL

IHYNG	1
IUNG	1
TAREA	25.48
SNAP	0.00
TRSDA	25.46
TRSPC	0.00
HYDROGRAPH DATA	
WATIO	0.009
ISNOV	0
ISAMF	1
LOCAL	0
JPLT	0
JPRY	0
IUNAF	1
ISTAGE	0
IAUTO	0
ISTAQ	1
ICOMP	0
IECON	0
ITAPE	0

	PMS	K6	PRECIP DATA	R72	R96
SPEE	0.00				
	22.40	104.00	R12 R24	R48	R72
			113.00 123.00	135.00	0.00

[illegible]

UNIT HYDROGRAPH DATA
TP= 12.00 CP= .58 NTA= 0

```

STRTO= -2.00      RECESSION DATA      RTIOR= 1.00
                ORCSN= 0.00

```

UNIT	HYDROGRAPH	75	END-OF-PERIOD	ORDINATES,	LAGE,	12.00	HOURS,	CP,	USE	VOL	1.00
15	170	197	229	707	43	220	549	17	01	00	00
16	170	197	264	707	43	220	549	17	01	00	00
17	170	197	349	707	43	220	549	17	01	00	00
18	170	197	453	707	43	220	549	17	01	00	00
19	170	197	533	707	43	220	549	17	01	00	00
20	170	197	623	707	43	220	549	17	01	00	00
21	170	197	723	707	43	220	549	17	01	00	00
22	170	197	823	707	43	220	549	17	01	00	00
23	170	197	923	707	43	220	549	17	01	00	00
24	170	197	1023	707	43	220	549	17	01	00	00
25	170	197	1123	707	43	220	549	17	01	00	00
26	170	197	1223	707	43	220	549	17	01	00	00
27	170	197	1323	707	43	220	549	17	01	00	00
28	170	197	1423	707	43	220	549	17	01	00	00
29	170	197	1523	707	43	220	549	17	01	00	00
30	170	197	1623	707	43	220	549	17	01	00	00
31	170	197	1723	707	43	220	549	17	01	00	00
32	170	197	1823	707	43	220	549	17	01	00	00
33	170	197	1923	707	43	220	549	17	01	00	00
34	170	197	2023	707	43	220	549	17	01	00	00
35	170	197	2123	707	43	220	549	17	01	00	00
36	170	197	2223	707	43	220	549	17	01	00	00
37	170	197	2323	707	43	220	549	17	01	00	00
38	170	197	2423	707	43	220	549	17	01	00	00
39	170	197	2523	707	43	220	549	17	01	00	00
40	170	197	2623	707	43	220	549	17	01	00	00
41	170	197	2723	707	43	220	549	17	01	00	00
42	170	197	2823	707	43	220	549	17	01	00	00
43	170	197	2923	707	43	220	549	17	01	00	00
44	170	197	3023	707	43	220	549	17	01	00	00
45	170	197	3123	707	43	220	549	17	01	00	00
46	170	197	3223	707	43	220	549	17	01	00	00
47	170	197	3323	707	43	220	549	17	01	00	00
48	170	197	3423	707	43	220	549	17	01	00	00
49	170	197	3523	707	43	220	549	17	01	00	00
50	170	197	3623	707	43	220	549	17	01	00	00
51	170										

MO. UA HR. PERIOD RAIN EXCS LOSS COMP G PERIOD FLOW MO. UA HR. PERIOD RAIN EXCS LOSS COMP G

SUM 24.80 19.82 4.98 33350. (630.)(503.)(126.)(9439.42)

.....

HYDROGRAPH ROUTING

ROUTING COMPUTATIONS - HOPATCONG

STAGE	523.30	924.30	925.30	926.30	927.70	928.70	929.70	930.70	931.70
FLOW	0.00	333.00	942.00	1730.00	3073.00	4497.00	6291.00	8355.00	10651.00
SURFACE AREA	2474.2644	2491.2661	2508.2525	2542.2542	2559.2559	2576.2576	2593.2593	2610.2610	2627.2627
CAPACITY	25330.0	2482.0	4982.0	7498.0	10032.0	12582.0	15150.0	17734.0	20336.0
ELEVATION	923.933	924.934	925.935	926.936	927.937	928.938	929.939	930.940	931.941

TOPFL 927.7
DAM DATA
C02D 0.0
EXPD 0.0
DAMWID 0.0

PEAK OUTFLOW IS 5640. AT TIME 65.00 HOURS

PEAK OUTFLOW IS 2120. AT TIME 69.00 HOURS

PEAK OUTFLOW IS 1574. AT TIME 70.00 HOURS

PEAK OUTFLOW IS 1070. AT TIME 71.00 HOURS

PEAK OUTFLOW IS 641. AT TIME 72.00 HOURS

PEAK OUTFLOW IS 211. AT TIME 75.00 HOURS

.....

END OF PERIOD FLOW

COMPUTE HYDROGRAPH - MUSCONETCONG LOCAL

ISTAQ 2 ICOMP 0 IECON 0 ITAPE 0 JPLT 0 JPR1 0 INAME 1 ISTAGE 0 IAUTO 0

INHYDG 1 IUNG 1 TARGA 1 SNAP 0.00 TRSDA 4.90 TRSPC 0.00 ISHOW 0 ISAME 0 LOCAL 0

PRECIP DATA
R12 R24 R48 R72 R96
0.00 22.40 112.00 123.00 132.00 142.00 0.00 0.00 0.00

LOSS DATA
STIRK3 0.00 RTIOL 1.00 ERAIN 0.00 STIRK1 1.00 ENSIL 0.15 ALSM1 0.00 RTIMP 0.00

UNIT HYDROGRAPH DATA
TP= 6.00 CPE= 5.8 NTA= 0

RECESSION DATA
STRIO= -2.00 QRCSE= 0.00 RTIOH= 1.00

UNIT HYDROGRAPH 37 END-OF-PERIOD ORDINATES, LAGE 6.00 HOURS, CP= .58 VOL= 1.00
19: 70: 140: 214: 276: 308: 274: 233: 198:
168: 143: 122: 101: 88: 75: 63: 54: 39:
33: 28: 20: 17: 15: 12: 11: 9: 8:
6: 5: 4: 3: 2: 1: 0: 0: 0:

MO.DA HR.MN PERIOD RAIN EXCS LOSS
END-OF-PERIOD FLOW
COMP 0 MO.DA HR.MN PERIOD RAIN EXCS LOSS COMP 0

SUM 25.45 20.64 4.41 66938.
(646.3) (524.3) (122.3) (1895.47)

COMBINE HYDROGRAPHS

COMBINE OUTFLOW OF HOPATCONG WITH LOCAL INFLOW OF MUSCONETCONG

ISTAQ 2 ICOMP 2 IECON 0 ITAPE 0 JPLT 0 JPR1 0 INAME 1 ISTAGE 0 IAUTO 0

ROUTING DATA
ROUTING DATA
IOPT 0 IPMP 0 LSTR 0

HYDROGRAPH ROUTING

ROUTING COMPUTATIONS - MUSCONETCONG

ISTAQ 3 ICOMP 1 IECON 0 ITAPE 0 JPLT 0 JPR1 0 INAME 1 ISTAGE 0 IAUTO 0

GLDSS 3.0 CLOS 0.00 AVG 0.00 TRSDA 4.90 TRSPC 0.00 ISHOW 0 ISAME 0 LOCAL 0

NSIPS 1 NSIOL 0 LAG 0.00 AMCKK 0.00 Y 0.00 STORA 0.00 ISPRAT -1

STAGE 85.75 86.75 87.75 88.75 89.75 90.75 91.75 92.75 93.75
FLOW 505.00 1445.00 3400.00 3460.00 3460.00 3460.00 3460.00 3460.00 3460.00

STAGE 86.75 87.75 88.75 89.75 90.75 91.75 92.75 93.75 94.75
FLOW 1445.00 3460.00 3460.00 3460.00 3460.00 3460.00 3460.00 3460.00 3460.00

SURFACE AREA= 310. 313. 316. 319. 322. 325. 328. 331. 334.
 CAPACITY= 0. 304. 934. 1252. 1572. 1896. 2222. 2552. 2884. 17
 ELEVATION= 860. 861. 862. 863. 864. 865. 866. 867. 868. 869.

CRFL SP-ID COQM FAFW FLEVL COUL CAREA EXPL
 459.4 0.0 0.0 0.0 0.0 0.0 0.0 0.0
 TOPEL COGD EXPD DAMWID
 863.5 0.0 0.0 0.0

PEAK OUTFLOW IS 5948. AT TIME 65.00 HOURS
 PEAK OUTFLOW IS 2527. AT TIME 49.00 HOURS
 PEAK OUTFLOW IS 1970. AT TIME 49.00 HOURS
 PEAK OUTFLOW IS 1495. AT TIME 49.00 HOURS
 PEAK OUTFLOW IS 907. AT TIME 49.00 HOURS
 PEAK OUTFLOW IS 405. AT TIME 51.00 HOURS

.....

CHANNEL ROUTING TO REACH 4

ISTAQ ICOMP 4 1
 WLOSS CLOSS AVG 0.00 0.00
 NSTPS NSTPL 1 0

HYDROGRAPH ROUTING

IECON ITAPE JPLT JPRY INAME ISTAGE IAUO
 0 0 0 0 1 0 0
 ROUTING DATA IOPT IPMP LSTR
 1 0 0 0
 LAG AMSKK X ISK STORA ISORAT
 0 0.000 0.000 0.000 0.000 0.000

.....

.....

NORMAL DEPTH CHANNEL ROUTING

QIN1 QIN2 QIN3 ELNVT ELMAX RLNTH SEL
 0.00 0.00 0.00 845.0 865.0 14000. 1460

CROSS SECTION COORDINATES--STA, ELEV, STA, FLEV--ETC
 0.00 870.00 2009.00 850.00 2009.00 847.00 2011.00 845.00 2016.00 845.00
 2018.00 847.00 2027.00 850.00 2400.00 840.00

STORAGE 0.00 0.00 10.00 9.14 15.61 26.02 80.13 194.47 364.72 603.09
 0.00 0.00 10.00 9.14 15.61 26.02 80.13 194.47 364.72 603.09

MAXIMUM STAGE IS 626.6
MAXIMUM STAGE IS 635.8
MAXIMUM STAGE IS 634.8
MAXIMUM STAGE IS 633.4
MAXIMUM STAGE IS 631.4

.....

SUR-AREA RUNOFF COMPUTATION

COMPUTE HYDROGRAPH - SEXTON LAKE LOCAL

ISTAG 5 ICOMP 0 IECON 0 ITAPE 0 JPLT 0 JPRT 0 INAME 1 ISTAGE 0 IAUTO 0

HYDROGRAPH DATA
IRSDA 0.00 IRSPC 0.000 RATIO 0 ISHOW 0 ISAME 0 LOCAL 0

PRECIP DATA
PMS 22.40 R6 100.00 R48 131.00 R72 0.00 R96 0.00

LOSS DATA
LNOPT 1 STKR 0.00 RTIOL 1.00 FRAM 0.00 STIRK 1.00 CNSTL 0.15 ALSHX 0.00 RIMP 0.00

UNIT HYDROGRAPH DATA
TP= 13.00 CPE= .58 MTA= 0

RECESSION DATA
STRIG= -2.00 ORCSN= 0.00 RTIOR= 1.00

UNIT HYDROGRAPH 86 END-OF-PERIOD OPINATES, LAGE 13.91 HOURS, CPE= .58 VOL= 1.00
1. 73. 150. 240. 340. 448. 561. 676. 785. 876.
943. 1003. 1038. 1052. 1038. 990. 925. 808. 755.
755. 659. 615. 575. 537. 502. 469. 438. 382.
357. 334. 291. 272. 254. 238. 222. 207. 194.
181. 169. 158. 148. 138. 129. 120. 105. 98.
92. 86. 80. 75. 70. 65. 61. 57. 50.
46. 43. 38. 35. 32. 29. 27. 25. 23.
24. 22. 19. 16. 14. 13. 12. 11. 10.

MO.DA HR.MN PERIOD RAIN EXCS LOSS END-OF-PERIOD FLOW MO.DA HR.MN PERIOD RAIN EXCS LOSS COMP 0
SUM 24.50 13.50 5.00 486934.
(622.3(495.3)(127.)(13788.44)

.....

COMBINE HYDROGRAPHS

COMBINE ROUTED OUTFLOW OF MUSCONETCONG WITH LOCAL INFLOW OF SEXTON

ISTAG 5 ICOMP 2 IECON 0 ITAPE 0 JPLT 0 JPRT 0 INAME 1 ISTAGE 0 IAUTO 0

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIO	RATIOS APPLIED TO FLOWS					
					1	2	3	4	5	6
				1.00	.50	.40	.30	.20	.10	
HYDROGRAPH AT	1	25.40	1	15026:	7513:	6010:	4508:	3005:	1503:	
	(65.79)	(425.48)	212.74)	170.19)	127.64)	85.10)	42.55)	
ROUTED TO	2	25.40	1	5640:	2120:	1574:	1079:	641:	261:	
	(65.79)	(159.70)	60.02)	44.57)	30.55)	18.14)	7.40)	
HYDROGRAPH AT	2	4.90	1	5580:	2790:	2232:	1674:	1116:	558:	
	(12.60)	(158.01)	79.01)	63.20)	47.40)	31.60)	15.80)	
2 COMBINED	2	30.30	1	6140:	3004:	2403:	1803:	1202:	601:	
	(78.48)	(173.86)	85.07)	68.06)	51.04)	34.03)	17.02)	
ROUTED TO	3	30.30	1	5948:	2527:	1970:	1445:	907:	405:	
	(78.48)	(168.42)	71.57)	55.79)	40.92)	25.67)	11.46)	
ROUTED TO	4	30.30	1	5945:	2499:	1946:	1425:	890:	404:	
	(78.48)	(168.35)	70.77)	55.10)	40.34)	25.20)	11.43)	
ROUTED TO	5	30.30	1	5925:	2456:	1913:	1408:	880:	401:	
	(78.48)	(167.77)	69.55)	54.18)	39.88)	24.91)	11.34)	
HYDROGRAPH AT	5	37.70	1	13182:	9591:	7673:	5755:	3436:	1918:	
	(97.54)	(543.18)	271.59)	217.27)	162.95)	108.64)	54.32)	
2 COMBINED	5	68.00	1	24141:	12015:	9565:	7137:	4714:	2319:	
	(176.12)	(683.60)	340.34)	270.80)	202.09)	133.49)	65.86)	
ROUTED TO	6	68.00	1	24135:	11997:	9548:	7116:	4699:	2306:	
	(176.12)	(683.43)	339.72)	270.36)	201.49)	133.07)	65.31)	

FLAG 1

RATIO OF PMF	ELEVATION STORAGE OUTFLOW	INITIAL VALUE	MAXIMUM RESERVOIR W.S. LEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTLOW HOURS	TIME OF FAILURE HOURS
1.00	929.34	925.00	1.64	15285.	5640.	37.00	65.00	0.00	0.00
.90	926.71	925.00	0.00	8389.	2120.	0.00	69.00	0.00	0.00
.80	926.17	925.00	0.00	6909.	1574.	0.00	70.00	0.00	0.00
.70	925.47	925.00	0.00	5418.	1075.	0.00	71.00	0.00	0.00
.60	924.80	925.00	0.00	3742.	641.	0.00	72.00	0.00	0.00
.50	924.08	925.00	0.00	1946.	261.	0.00	75.00	0.00	0.00

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION OF STORAGE OUTFLOW	INITIAL VALUE 859.75 0. 0.	SPILLWAY CREST 859.75 0. 0.	TOP OF DAM 863.50 1172. 3460.			
RATIO OF PME	MAXIMUM RESERVOIR U.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	865.34	1.84	1761.	5948.	46.00	65.00	0.00
.50	862.17	0.00	752.	2527.	0.00	49.00	0.00
.40	861.80	0.00	636.	1970.	0.00	49.00	0.00
.30	861.40	0.00	511.	1445.	0.00	49.00	0.00
.20	860.38	0.30	381.	907.	0.00	49.00	0.00
.10	860.42	0.00	206.	405.	0.00	51.00	0.00

PLAN 1 STATION 4

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
1.00	5945.	653.4	65.00
.50	2499.	652.1	50.00
.40	1946.	651.8	50.00
.30	1425.	651.5	50.00
.20	890.	650.8	51.00
.10	404.	649.4	51.00

PLAN 1 STATION 5

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
1.00	5925.	639.4	67.00
.50	2456.	636.6	51.00
.40	1913.	635.8	51.00
.30	1408.	634.8	51.00
.20	880.	633.4	52.00
.10	401.	631.4	53.00

PLAN 1

RATIO OF PHE	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 92.35 0.0 0.0	SPILLWAY CREST 92.35 0.0 0.0	TOP OF DAM 97.55 374. 5474.	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	104.34	6.79	106.1		0.0	53.00	0.00
1.20	100.42	2.67	93.25		25.00	53.00	0.00
1.40	98.46	1.24	84.47		19.00	53.00	0.00
1.60	96.59	0.84	74.16		11.00	53.00	0.00
1.80	94.95	0.50	66.99		0.00	53.00	0.00
2.00	93.34	0.33	62.30		0.00	53.00	0.00

FLOOD HYDROGRAPH PACKAGE (HEC-1)
DAM SAFETY VERSION JULY 1978
LAST MODIFICATION 11 JAN 79

APPENDIX 4

REFERENCES

SAXTON FALLS DAM

APPENDIX 4

REFERENCES

SAXTON FALLS DAM

1. Letter to Dr. H.B. Kummel, Director, Dept. of Conservation & Development, from C.C. Vermeule, Morris Canal & Banking Co., dated 11 Feb. 1927.
2. Letter to Mr. C.C. Vermeule from J.N. Brooks, Hydraulic Engineer, Dept. of Conservation & Development, dated 18 Feb. 1927.
3. Letter to Mr. J.N. Brooks from C.C. Vermeule, dated 7 March 1927.
4. Inspection Report by J.N. Brooks, dated 8 March 1927.
5. Letter to Mr. C.C. Vermeule from J.N. Brooks, dated 10 March 1927.
6. Letter to Mr. J.N. Brooks from C.C. Vermeule, dated 14 July 1927.
7. Inspection Report by J.N. Brooks, Hydraulic Engineer, dated 23 July 1927.
8. Monthly Progress Report by C.C. Vermuele, dated 31 July 1927.
9. Letter to Mr. J.N. Brooks from C.C. Vermeule, dated 7 November 1927.
10. Inspection Report by J.N. Brooks, Hydraulic Engineer, dated 11 May 1928.
11. Memorandum to C.P. Wilbur, State Forester, from H.T. Critchlow, Director, Div. of Water Policy & Supply, dated 14 July 1953.
12. Annual Report by M. Berkowitz, P.E., dated 5 June 1968.
13. Memorandum to G.R. Shanklin, Director & Chief Engineer, Div. of Water Policy & Supply, from J.J. Truncer, Director, Div. of Parks, Forestry & Recreation, dated 26 June 1968.
14. Inspection Report by S.A. Aziz, dated 28 May 1971.
15. Chow, Ven Te, Ph.D, Open Channel Hydraulics, McGraw-Hill Book Company, 1959.
16. United States Dept. of Agriculture, Soil Conservation Service SCS National Engineering Handbook Section 4 Hydrology NEH-Notice 4-102, August 1972.

17. United States Dept. of Agriculture, Soil Conservation Service, Somerset, N.J. Urban Hydrology for Small Watersheds, Technical Release No. 55, January 1975.
18. United States Dept. of Commerce Weather Bureau, April 1956 Hydrometeorological Report No. 33, Washington, D.C.
19. United States Dept. of Interior, Bureau of Reclamation Design of Small Dams, Second Edition 1973, Revised Print 1977.
20. Wolfe, P.E., 1977, The Geology and Landscapes of New Jersey, Crane, Russak & Company, Inc., New York, New York, 351 pp.

DRAWINGS

1. Dwg. No 522, Profile & Sections-Old Dam & MC52, by Morris Canal & Banking Co., dated 6 April 1926.
2. Dwg. No 523, Cross Sections Near Saxton Falls Dam, by Morris Canal & Banking Co., dated 26 Sept. 1926.
3. Dwg. No 524, Cross Sections Elevation-Gatehouse, by Morris Canal & Banking Co., dated 1 October 1926.
4. Dwg. No 525, Plan Elevation & Sections-Saxton Dam, by Morris Canal & Banking Co., dated 20 Nov. 1926.
5. Dwg. No 521, General Plan Saxton Falls Dam, by Morris Canal & Banking Co., dated 9 April 1926.